HF52

Firmware Version 3.1

Release Notes 27.10.2015

Enhancements:

- Automatic exit the menu after 60 seconds.

Bugs fixed:

- Bug: Display can freeze. Bug is fixed now.

Known bugs:

- none

Notes:

- From PCB Number: 66.0864.0601 is only an update with ROF File possible. **HEX Files works only on the old PCB and the latest update is the V2.0 Firmware.**

ROTRONIC AG, Grindelstrasse 6, CH - 8303 Bassersdorf
Tel. +41 44 838 11 11, Fax +41 44 836 44 24, www.rotronic.ch

rotronic
MEASUREMENT SOLUTIONS